REC'D. IOWA

FEB 18 1994

OMB#: 2050-0024 Expires 8/31/96

IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
JESSE TRENT
PO BOX 370

POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM IC

IDENTIFICATION AND CERTIFICATION

INSTRUCTIONS: Read the detailed instructions beginning on page 9 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I Site name and location address. Complete A through H. Check the box ☐ in items A, C, E, F, G, and H if same as label; if different, enter corrections. If label is absent, enter information. Instruction page 10.

A. EPA ID No. Same as label ☒ or →	B. County: Allamakee
C. Site/company name Same as label ☒ or →	D. Has the site name associated with this EPA ID changed since 1981? ☒ 1 Yes ☐ 2 No
E. Street name and number. If not applicable, enter industrial park, building name, or other physical location description. Same as label ☐ or → 665 Lybrand St.	
F. City, town, village, etc. Same as label ☒ or →	G. State Same as label: IA
	H. Zip Code Same as label: 52152-0370

Sec. II Mailing address of site. Instruction page 10.

A. Is the mailing address the same as the location address? ☐ 1 Yes (SKIP TO SEC. III) ☒ 2 No (GO TO BOX B)

R00330195
RCRA RECORDS CENTER

B. Number and street name of mailing address: PO Box 370	
C. City, town, village, etc.: Postville	D. State: IA
	E. Zip Code: 52162-0370

Sec. III Name, title, and telephone number of the person who should be contacted if questions arise regarding this report. Instruction page 10.

A. Please print: Last Name	First name	M.I.	B. Title	C. Telephone
Trent	Jesse	C	EH&S Specialist	319-864-7321 Extension

Sec. IV "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate and complete. I am aware that there are significant penalties under Section 3008 of the Resource Conservation and Recovery Act for submitting false information, including the possibility of fine and imprisonment for knowing violations."

FILE COPY
IAD073489288
DOCUMENT # 82A

A. Please print: Last Name	First name	M.I.	B. Title	C. Signature	D. Date of signature
Gilbert	Jim	W	Plant Manager	James W. Gilbert	02 15 94 (MO. DAY YR.)

Sec.V - Generator Status

EPA ID NO. I A D 0 7 3 4 8 9 2 8 8

A. 1993 RCRA generator status
Instruction page 10.
(CHECK ONE BOX BELOW)

- [X] 1 LQG
- [ ] 2 SQG
- [ ] 3 CESQG

SKIP to SEC. VI

- [ ] 4 Non generator (Continue to Box B)

B. Reason for not generating
Page 12.
(CHECK ALL THAT APPLY)

- [ ] 1 Never generated
- [ ] 2 Out of business
- [ ] 3 Only excluded or delisted waste
- [ ] 4 Only non-hazardous waste
- [ ] 5 Periodic or occasional generator
- [ ] 6 Waste minimization activity
- [ ] 7 Other (SPECIFY COMMENTS IN BOX BELOW)

Sec.VI - On-Site Waste Management Status

A. Storage subject to RCRA permitting requirements Page 13.	B. Treatment, disposal, or recycling subject to RCRA permitting requirements Page 13.	C. RCRA-exempt treatment, disposal, or recycling Page 13.
1	1	3

Sec.VII - Waste Minimization Activity during 1992 or 1993

A. Did this site begin or expand a source reduction activity during 1992 or 1993? Page 14.	B. Did this site begin or expand a recycling activity during 1992 or 1993? Page 15.	C. Did this site systematically investigate opportunities for source reduction or recycling during 1992 or 1993? Page 15.
[ ] 1 Yes [X] 2 No	[ ] 1 Yes [X] 2 No	[X] 1 Yes [ ] 2 No

D. Did any of the factors listed below delay or limit this site's ability to initiate new or additional source reduction activities in 1992 or 1993? Page 15
(CHECK YES OR NO FOR EACH ITEM)

Yes	No		
[X] 1	[ ] 2	a.	Insufficient capital to install new source reduction equipment or implement new source reduction practices
[ ] 1	[X] 2	b.	Lack of technical information on source reduction techniques applicable to the specific production processes
[ ] 1	[X] 2	c.	Source reduction is not economically feasible: cost savings in waste management or production will not recover the capital investment
[X] 1	[ ] 2	d.	Concern that product quality may decline as a result of source reduction
[X] 1	[ ] 2	e.	Technical limitations of the production processes
[ ] 1	[X] 2	f.	Permitting burdens
[ ] 1	[X] 2	g.	Source reduction previously implemented - additional reduction does not appear to be technically feasible
[ ] 1	[X] 2	h.	Source reduction previously implemented - additional reduction does not appear to be economically feasible
[ ] 1	[X] 2	i.	Source reduction previously implemented - additional reduction does not appear to be feasible due to permitting requirements
[ ] 1	[X] 2	j.	Other (SPECIFY COMMENTS IN BOX BELOW)

E. Did any of the factors listed below delay or limit the site's ability to initiate new or additional on-site or off-site recycling activities during 1992 or 1993? Page 15.
(CHECK YES OR NO FOR EACH ITEM)

Yes	No		
[ ] 1	[X] 2	a.	Insufficient capital to install new recycling equipment or implement new recycling practice
[ ] 1	[X] 2	b.	Lack of technical information on recycling techniques applicable to this site's specific production process
[ ] 1	[X] 2	c.	Recycling is not economically feasible: cost savings in waste management will not recover the capital investment
[X] 1	[ ] 2	d.	Concern that product quality may decline as a result of recycling
[ ] 1	[X] 2	e.	Requirements to manifest wastes inhibit shipments of off-site for recycling
[ ] 1	[X] 2	f.	Financial liability provisions inhibit shipments off-site for recycling
[ ] 1	[X] 2	g.	Technical limitations of production processes inhibit shipments off-site for recycling
[X] 1	[ ] 2	h.	Technical limitations of production processes inhibit on-site recycling
[ ] 1	[X] 2	i.	Permitting burdens inhibit recycling
[ ] 1	[X] 2	j.	Lack of permitted off-site recycling facilities
[ ] 1	[X] 2	k.	Unable to identify a market for recycled materials
[ ] 1	[X] 2	l.	Recycling previously implemented - additional recycling does not appear to be technically feasible
[ ] 1	[X] 2	m.	Recycling previously implemented - additional recycling does not appear to be economically feasible
[ ] 1	[X] 2	n.	Recycling previously implemented - additional recycling does not appear to be feasible due to permitting requirements
[ ] 1	[X] 2	o.	Other (SPECIFY COMMENTS IN BOX BELDW)

Comments:

BEFORE COPYING FORM, PLEASE READ

IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
SITE JESSE TRENT
PO BOX 370
EPA ID NO.
POSTVILLE, IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

INSTRUCTIONS: Read the detailed instructions beginning on page 16 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I

A. Waste description - Instruction page 18. Still bottoms from solvent recovery batch distillation unit containing small amounts of acetone, toluene & other various solvents.

B. EPA hazardous waste code Page 19.
F 0 0 3 F 0 0 5
D 0 0 1 N A N A

C. State hazardous waste code Page 19.

D. SIC code Page 19.	E. Origin code / System Type Page 19	F. Source code Page 20.	G. Point of measurement Page 20.	H. Form code Page 20.	I. RCRA - radioactive mixed Page 20.
3 0 8 3	M	A 7 3	1	B 6 0 2	2

Sec. II

A. Quantity generated in 1992 Instruction Page 21.	B. Quantity generated in 1993 Page 21.	C. UOM Page 21. / Density	D. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? Page 21.
3 8 9 0 7 . 0	4 8 8 6 0 . 0	1 / 0 . 0 ☐ 1 lbs/gal ☐ 2 sg	☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (SKIP TO SEC. III)

ON-SITE PROCESS SYSTEM 1

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	.

ON-SITE PROCESS SYSTEM 2

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	.

Sec. III

A. Was any of this waste shipped off-site in 1993 Instruction page 23. ☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (SKIP TO SEC IV)

	B. EPA ID No. of facility waste was shipped to Page 23.	C. System type shipped to Page 23.	D. Off-site availability code Page 23.	E. Total quantity shipped in 1993 Page 23.
Site 1	I L D 9 8 0 6 1 3 9 1 3	M 0 6 1	1	4 8 6 0 . 0
Site 2		M		.

Sec. IV

A. Did new activities in 1993 result in minimization of this waste? Instruction page 24. ☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (THIS FORM IS COMPLETE)

B. Activity Page 24.	C. Other effects Page 24.	D. Quantity recycled in 1993 due to new activities Page 25.	E. Activity/production index Page 25.	F. 1993 source reduction quantity Page 26.
W / W W / W	☐ 1 Yes ☐ 2 No	.	.	.

Comments:

BEI IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
SIT JESSE TRENT
PO BOX 370
EPA
POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

INSTRUCTIONS: Read the detailed instructions beginning on page 16 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I A. Waste description - Instruction page 18. Ignitable solvent used for parts washer, contains petroleum naptha.

B. EPA hazardous waste code Page 19. D039 D018

C. State hazardous waste code Page 19.

D. SIC code Page 19.	E. Origin code Page 19 / System Type	F. Source code Page 20.	G. Point of measurement Page 20.	H. Form code Page 20.	I. RCRA - radioactive mixed Page 20.
3083	1 / M	A09	1	B203	2

Sec. II

A. Quantity generated in 1992 Instruction Page 21.	B. Quantity generated in 1993 Page 21.	C. UOM Page 21. / Density	D. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? Page 21.
4310.0	4087	1 / ☐ 1 lbs/gal ☐ 2 sg	☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (SKIP TO SEC. III)

ON-SITE PROCESS SYSTEM 1		ON-SITE PROCESS SYSTEM 2	
On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993	On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M		M	

Sec. III A. Was any of this waste shipped off-site in 1993 Instruction page 23. ☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (SKIP TO SEC IV)

	B. EPA ID No. of facility waste was shipped to Page 23.	C. System type shipped to Page 23.	D. Off-site availability code Page 23.	E. Total quantity shipped in 1993 Page 23.
Site 1	WID980896641	M029	1	4087
Site 2		M		

Sec. IV A. Did new activities in 1993 result in minimization of this waste? Instruction page 24. ☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (THIS FORM IS COMPLETE)

B. Activity Page 24.	C. Other effects Page 24.	D. Quantity recycled in 1993 due to new activities Page 25.	E. Activity/production index Page 25.	F. 1993 source reduction quantity Page 26.
W / W / W / W	☐ 1 Yes ☐ 2 No			

Comments:

BEI IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
SIT JESSE TRENT
PO BOX 370
EPI
POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

INSTRUCTIONS: Read the detailed instructions beginning on page 16 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I A. Waste description - Instruction page 18. Spent Ferric Chloride solution from acid etcher used for product testing. Solution is corrosive.

B. EPA hazardous waste code Page 19.
D002 D007
NA NA NA

C. State hazardous waste code Page 19.

D. SIC code Page 19.	E. Origin code 1 Page 19 / System Type M	F. Source code Page 20.	G. Point of measurement Page 20.	H. Form code Page 20.	I. RCRA - radioactive mixed Page 20.
3083		A27	1	B103	2

Sec. II

A. Quantity generated in 1992 Instruction Page 21.	B. Quantity generated in 1993 Page 21.	C. UOM Page 21. / Density	D. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? Page 21.
6750.0	7200.0	1 / . / 1 lbs/gal 2 sg	1 Yes (CONTINUE TO SYSTEM 1) 2 No (SKIP TO SEC. III)

ON-SITE PROCESS SYSTEM 1

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	

ON-SITE PROCESS SYSTEM 2

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	

Sec. III A. Was any of this waste shipped off-site in 1993 Instruction page 23. 1 Yes (CONTINUE TO BOX B) 2 No (SKIP TO SEC IV)

	B. EPA ID No. of facility waste was shipped to Page 23.	C. System type shipped to Page 23.	D. Off-site availability code Page 23.	E. Total quantity shipped in 1993 Page 23.
Site 1	MID008011002	M079	1	7200.0
Site 2		M		

Sec. IV A. Did new activities in 1993 result in minimization of this waste? Instruction page 24. 1 Yes (CONTINUE TO SYSTEM 1) 2 No (THIS FORM IS COMPLETE)

B. Activity Page 24.	C. Other effects Page 24.	D. Quantity recycled in 1993 due to new activities Page 25.	E. Activity/production index Page 25.	F. 1993 source reduction quantity Page 26.
W W W W	1 Yes 2 No			

Comments:

BEI IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
SIT JESSE TRENT
PO BOX 370
EPI POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

INSTRUCTIONS: Read the detailed instructions beginning on page 16 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I A. Waste description - Instruction page 18. Ignitable liquid, mixture contains rags, acetone, toluene from treater clean up.

B. EPA hazardous waste code Page 19.
D001 F005
NA NA NA

C. State hazardous waste code Page 19.

D. SIC code Page 19.	E. Origin code 1 Page 19 / System Type M	F. Source code Page 20.	G. Point of measurement Page 20.	H. Form code Page 20.	I. RCRA - radioactive mixed Page 20.
3083		A09		B2013	2

Sec. II A. Quantity generated in 1992 Instruction Page 21. 1510.0

B. Quantity generated in 1993 Page 21. 6000.0

C. UOM Page 21. 1 (☐ 1 lbs/gal ☐ 2 sg) Density

D. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? Page 21.
☐ 1 Yes (CONTINUE TO SYSTEM 1)
☒ 2 No (SKIP TO SEC. III)

ON-SITE PROCESS SYSTEM 1
On-site process system type Page 22. M
Quantity treated, disposed, or recycled on site in 1993

ON-SITE PROCESS SYSTEM 2
On-site process system type Page 22. M
Quantity treated, disposed, or recycled on site in 1993

Sec.III A. Was any of this waste shipped off-site in 1993 Instruction page 23.
☒ 1 Yes (CONTINUE TO BOX B)
☐ 2 No (SKIP TO SEC IV)

	B. EPA ID No. of facility waste was shipped to Page 23.	C. System type shipped to Page 23.	D. Off-site availability code Page 23.	E. Total quantity shipped in 1993 Page 23.
Site 1	ILD980613913	M061	1	6000.0
Site 2		M		

Sec. IV A. Did new activities in 1993 result in minimization of this waste? Instruction page 24.
☐ 1 Yes (CONTINUE TO SYSTEM 1)
☒ 2 No (THIS FORM IS COMPLETE)

B. Activity Page 24.	C. Other effects Page 24.	D. Quantity recycled in 1993 due to new activities Page 25.	E. Activity/production index Page 25.	F. 1993 source reduction quantity Page 26.
W W W W	☐ 1 Yes ☐ 2 No			

Comments:

BEI IAD073489288
ALLIEDSIGNAL LAMINATE SYSTEMS
SITE JESSE TRENT
PO BOX 370
EPA ID NO.
POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM GM

WASTE GENERATION AND MANAGEMENT

INSTRUCTIONS: Read the detailed instructions beginning on page 16 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I A. Waste description - Instruction page 18. Ignitable solvent mixture from process cleanup and distillation process. Contains Acetone/toluene.

B. EPA hazardous waste code Page 19.
F003 F005
D001 D007 D008

C. State hazardous waste code Page 19.

O. SIC code Page 19.	E. Origin code 5 Page 19 / System Type M021	F. Source code Page 20.	G. Point of measurement Page 20.	H. Form code Page 20.	I. RCRA - radioactive mixed Page 20.
3083		A73	1	B203	2

Sec. II

A. Quantity generated in 1992 Instruction Page 21.	B. Quantity generated in 1993 Page 21.	C. UOM Page 21. / Density	D. Did this site do any of the following to this waste: treat on site, dispose on site, recycle on site, or discharge to a sewer/POTW? Page 21.
151800.0	880000.0	1 / . / ☐ 1 lbs/gal ☐ 2 sg	☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (SKIP TO SEC. III)

ON-SITE PROCESS SYSTEM 1

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	.

ON-SITE PROCESS SYSTEM 2

On-site process system type Page 22.	Quantity treated, disposed, or recycled on site in 1993
M	.

Sec.III A. Was any of this waste shipped off-site in 1993 Instruction page 23. ☒ 1 Yes (CONTINUE TO BOX B) ☐ 2 No (SKIP TO SEC IV)

	B. EPA ID No. of facility waste was shipped to Page 23.	C. System type shipped to Page 23.	D. Off-site availability code Page 23.	E. Total quantity shipped in 1993 Page 23.
Site 1	ILD 980613913	M061	1	880000.0
Site 2		M		.

Sec. IV A. Did new activities in 1993 result in minimization of this waste? Instruction page 24. ☐ 1 Yes (CONTINUE TO SYSTEM 1) ☒ 2 No (THIS FORM IS COMPLETE)

B. Activity Page 24.	C. Other effects Page 24.	D. Quantity recycled in 1993 due to new activities Page 25.	E. Activity/production index Page 25.	F. 1993 source reduction quantity Page 26.
W W W W	☐ 1 Yes ☐ 2 No	.	.	.

Comments:
D035

BEFORE COPYING FORM, ATTACH SITE IDENTIFICATION LABEL OR ENTER:

IAD073489288

SITE NAME
ALLIEDSIGNAL LAMINATE SYSTEMS
JESSE TRENT
PO BOX 370
EPA ID NO:
POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM PS

WASTE TREATMENT, DISPOSAL, OR RECYCLING PROCESS SYSTEMS

INSTRUCTIONS: Read the detailed instructions beginning on page 33 of the 1993 Hazardous Waste Report booklet before completing this form.

Sec. I

A. Waste treatment, disposal, or recycling system description
Instruction Page 39. Solvent Recovery through Distillation Process

B. System type Page 38.	C. Regulatory status Page 39.	D. Operational status Page 39.	E. Unit types Page 39.
M 021	08	01	01

Sec. II

A. 1993 influent quantity
Instruction page 40.

	Total	UOM	Density
Total	8877.0	5	6.8
RCRA	8877.0		X 1 lbs/gal ☐ 2 sg

B. Maximum operational capacity
Page 41.

	Total
Total	16555.0
RCRA	16555.0

C. 1993 liquid effluent quantity
Instruction page 42.

	Total	UOM	Density
Total	0.0		
RCRA	0.0		☐ 1 lbs/gal ☐ 2 sg

D. 1993 solid/sludge residual quantity
Page 42.

	Total	UOM	Density
Total	0.0		
RCRA	0.0		☐ 1 lbs/gal ☐ 2 sg

E. Limitation on maximum operational capacity
Page 43.
1. 09 2. 3.

F. Commercial capacity availability code
Page 43.
1

G. Percent capacity commercially available
Page 43.
0 %

Comments:

IAD073489288

ALLIEDSIGNAL LAMINATE SYSTEMS
JESSE TRENT
PO BOX 370

POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM 0I

OFF-SITE IDENTIFICATION

INSTRUCTIONS: Read the detailed instructions on the reverse side before completing this form.

Site 1
A. EPA ID No. of off-site installation or transporter: MID 098 011 912
B. Name of off-site installation or transporter: Cyanoken Ind.
C. Handler type (CHECK ALL THAT APPLY): ☐ Generator ☐ Transporter ☒ TSDR
D. Address of generator: Street 12381 Schafer Highway; City Detroit; State MI Zip 48227-

Site 2
A. EPA ID No. of off-site installation or transporter: WID 980 896 641
B. Name of off-site installation or transporter: Safety-Kleen Corp.
C. Handler type (CHECK ALL THAT APPLY): ☐ Generator ☐ Transporter ☒ TSDR
D. Address of generator: Street 2109 1/2 Ward Ave.; City LaCrosse; State WI Zip 54601-

Site 3
A. EPA ID No. of off-site installation or transporter: ILD 980 613 913
B. Name of off-site installation or transporter: Safety-Kleen Enviro Systems
C. Handler type (CHECK ALL THAT APPLY): ☐ Generator ☒ Transporter ☒ TSDR
D. Address of generator: Street 633 E. 138th St.; City Dolton; State IL Zip 60419-

Site 4
A. EPA ID No. of off-site installation or transporter: OHD 009 865 825
B. Name of off-site installation or transporter: Dart Trucking Company
C. Handler type (CHECK ALL THAT APPLY): ☐ Generator ☒ Transporter ☐ TSDR
D. Address of generator: Street 61 Railroad St.; City Canfield; State OH Zip 44406-

Site 5
A. EPA ID No. of off-site installation or transporter: WID 980 904 742
B. Name of off-site installation or transporter: Schneider Tank Lines Inc.
C. Handler type (CHECK ALL THAT APPLY): ☐ Generator ☒ Transporter ☐ TSDR
D. Address of generator: Street 3101 S. Packerland Dr.; City Green Bay; State WI Zip 54304-

Comments:

IAD073489288

ALLIEDSIGNAL LAMINATE SYSTEMS
JESSE TRENT
PO BOX 370

POSTVILLE,IA 521620370

U.S. ENVIRONMENTAL PROTECTION AGENCY

1993 Hazardous Waste Report

FORM 01

OFF-SITE IDENTIFICATION

INSTRUCTIONS: Read the detailed instructions on the reverse side before completing this form.

Site 1

A. EPA ID No. of off-site installation or transporter: W I D 9 8 8 5 6 6 2 4 6

B. Name of off-site installation or transporter: Alliance Transportation Services, Inc.

C. Handler type (CHECK ALL THAT APPLY)
- ☐ Generator
- ☒ Transporter
- ☐ TSDR

D. Address of generator
Street: 140 South Park St.
City: Port Washington
State: W I Zip: 5 3 0 7 4 -

Site 2

A. EPA ID No. of off-site installation or transporter:

B. Name of off-site installation or transporter:

C. Handler type (CHECK ALL THAT APPLY)
- ☐ Generator
- ☐ Transporter
- ☐ TSDR

D. Address of generator
Street:
City:
State: Zip: -

Site 3

A. EPA ID No. of off-site installation or transporter:

B. Name of off-site installation or transporter:

C. Handler type (CHECK ALL THAT APPLY)
- ☐ Generator
- ☐ Transporter
- ☐ TSDR

D. Address of generator
Street:
City:
State: Zip: -

Site 4

A. EPA ID No. of off-site installation or transporter:

B. Name of off-site installation or transporter:

C. Handler type (CHECK ALL THAT APPLY)
- ☐ Generator
- ☐ Transporter
- ☐ TSDR

D. Address of generator
Street:
City:
State: Zip: -

Site 5

A. EPA ID No. of off-site installation or transporter:

B. Name of off-site installation or transporter:

C. Handler type (CHECK ALL THAT APPLY)
- ☐ Generator
- ☐ Transporter
- ☐ TSDR

D. Address of generator
Street:
City:
State: Zip: -

Comments:

February 15, 1994

To: Elizabeth Koesterer
USEPA
726 Minnesota Avenue
Kansas City, KS 66101

From: Jesse Trent
Environmental, Health and Safety Specialist

RE: SARA 313 Biennial Hazardous Waste Reports

Enclosed please find AlliedSignal Laminate System Biennial Hazardous Waste Reports for the Postville, Iowa facility.

Thank you,

Jesse Trent

Jesse Trent
AlliedSignal
P.O. Box 977
665 Lybrand St.
Postville, IA 52162